
FORESTHILL ROAD BRIDGE PAINTING

PROJECT NO. 2698 SUPERVISORIAL DISTRICT 5





- VICINITY MAP -

- VIEW OF BRIDGE LOOKING EASTERLY -

PROJECT DESCRIPTION

The bridge has not been painted since its construction in the early 70's. The existing paint is breaking down in many areas. If deterioration of the paint is not corrected, it will continue and adversely affect the structure. The proposed solution is to remove existing areas of failing paint and repaint the entire structure.

Totals

PROGRAMMED ACTIVITY

	BEC	ilM CO	NTINUE COMPLETE
DESIGN/ENVIRON	\circ	\odot	0
RIGHT-OF-WAY	\circ	0	0
CONSTRUCTION	\circ	0	0

FISCAL INFORMATION

Co	Cost thru		Budget		Estimated	
FY	FY 06/07		FY 07/08		<u>ject Total</u>	
\$	90,000	\$	40,000	\$	254,000	
\$	0	\$	0	\$	0	
\$	0	\$	0	<u>\$ 8</u>	<u>3,400,000</u>	
\$	90.000	\$	40.000	\$ 8	3.654.000	

PROPOSED CONSTRUCTION YEAR

(Depending on	Funding	Availability—		
uncertain)				

FUNDING SOURCES/AMOUNTS

HBRR Grant	\$ 6,923,200
Road Funds	<u>\$ 1,730,800</u>
Total	\$ 8,654,000

Project Manager: Kevin Ordway 530-745-3576